

Singing Cat Services

Service Report

Work Completed: May 2023

ARP Omni-2-s/n 2471-15 - "dash" is indistinct-could be "8", 11011 or factory change?

Synth has been completely recapped % J. Walker-very recent replacements plus new PSU components have been previously installed. Very Good condition-check key bushings/contacts & key-heights.

Full test TB scheduled 29-3-23.

Cleaned all key-contacts with IPA/De-Ox & same with bus-bars.

Cleaned & re-lubed all sliders, controls & switches.

Removed all IC wire headers to clean & abraid where necessary.

Full test completed 31-3-23-replaced missing rubber foot & repaired another ok.

I

Recommendations-same as with the ARP/Minimoog though in the Omni there are also TOS and Divider ics, some of which have not been available an here/at any price as new or used for at least a decade.

The recapping/power supply will definitely protect those ics from spiking/failures that occur a lot in the Omni/Solina ranges.